
Cam Degree Installation Fixture



HARD STOP FOR SETTING TOP DEAD CENTER.

If you prefer to use the Dial Indicator method of setting t.d.c, simply drill out the existing hole to 3/8" Diameter to fit your indicator.

NOTE: DO NOT Over-tighten your indicator screws or you may damage your indicator